

Inspection Order No.: IN-TJ-PSI-11109

Boss No.: 11810601 Page No.: 1 of 4

Date of issue: May 14, 2011

**INSPECTION REPORT** 

(non-negotiable) - Description and Quantity of

Commodity:

Alloy steel tubes according to ASTM A213-T9/1200pieces

- Name & Address Of Buyer: PETROLEOS DEL PERU-PETROPERU S.A.

AV.PASEO DE LA REPUBLICA NO 3361

LIMA 27 PERU

- Name & Address Of Seller: CHENGDU DERBO STEEL CO.,LTD

ADD:ROOM NO.1025 MEINIAN PLAZA TIANFU AVENUE

CHENGDU CITY CHINA

TEL:+86-28-85223949 FAX:+86-28-85249639

May 7, 2011, in Cangzhou City, China - Inspection Date & Place:

777-01-0029098-P Date of Issue: 110423 - L/C No.:

a) Visual quality inspection randomly - Nature Of Inspection:

b) Packing and marking check randomly

c) Dimension check randomly

d) Lab test for mechanical properties e) Lab test for chemical analysis

- Inspector: Marshall Yang

This is to report that we, SGS-CSTC Tianjin Branch on May 7, 2011 at the request of Chengdu Derbo Steel Co.,LTD conducted the following inspection:

## **Identification:**

During the inspection, the following cargos were presented on inspection site:

Alloy steel tubes: 114.3mm\*6mm\*6M/ 120 pieces

#### Disclaimer

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms\_and\_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.



## **Inspection Finding:**

1. Visual quality inspection randomly: (sample size: ANSI / ASQ Z1.4-2003, L-II, 20pcs ttally)

During the inspection, the pipes were selected randomly for visual quality check. The pipes were painted with black varnish. Both ends were plain end. One end of 1 piece of pipe was slight bevel end. Manufacturer declared that they will repair it before shipment.

- 2. Packing and marking check randomly: (sample size: ANSI / ASQ Z1.4-2003, L-II, 20pcs tbally)
- 2.1 Packing check:

The pipes were nude packing.

2.2 Marking check:

#### ASTM A213 T9 114.3×6.02×6M HEAT NO.:62342

3. Dimension check randomly: (sample size: according to ANSI / ASQ Z1.4-2003, S-4, 20pcs totally)

(Unit: mm)

Size		Outside diameter	Wall thickness	length
114.3×6.02×6000	Required value	114.3(+0.4,-0.8)	6.02-8.13	6000(+5,0)
	Actual value	114.5-114.7	6.02-6.3	6004-6005

# Remark:

- 1) The required values were specified in ASTM A 450/A 450M-07.
- 2) The calibrated record of measure instrument which was used in the inspection was not provided by manufacturer. The actual values were for client reference.

#### 4. Lab test:

1pc of sample was taken from manufacturer and performed lab test in SGS Material Lab, the test result was specified in test report (No.: TM905044 dated: May.14, 2011), the details were as following:

4.1Test item: Chemical composition analysis

Test method: OES

Spec.	Element,%						
	C	Si	Mn	Р	S	Cr	Мо
114.3mm×6mm	0.14	0.32	0.32	0.012	0.001	8.65	0.97
Requirement*,%	≤0.15	0.25~1.00	0.30~0.60	≤0.025	≤0.025	8.00~10.00	0.90~1.10
Conclusion	Pass	Pass	Pass	Pass	Pass	Pass	Pass

Note:\*Specified in ASTM A213/A213M-04 (T9)

Inspection Order No.: IN-TJ-PSI-09109 Page No.: 2 of 4



4.2 Test item: Mechanical properties test Test method: ASTM E8-04

Test item	result 114.3*6mm	Requirement*	Conclusion	
Yield strength, R <sub>p0.2</sub> MPa	251	≧205	Pass	
Tensile strength, R <sub>m</sub> MPa	561	≧415	Pass	
Elongation after fracture, (A <sub>50mm</sub> ) %	32.5	≧30	Pass	

Note: \* specified in ASTM A213/A213M-04 (T9)

5. Referred photos:





Slight beveled at the end



Packing check



Marking check

Dimension check

# SGS





Dimension check

Dimension check

THIS REPORT ONLY REFLECTED OUR ACTUAL FINDINGS. THE INSPECTION WAS DONE TO THE BEST OF OUR KNOWLEDGE AND ABILITY AND WITH DUE CARE. THE FINDINGS ARE VALID AS FOR TIME AND PLACE OF INSPECTION.